

Tech Tip

Engine stops running in wet conditions

There have been reports that some riders have experienced unexpected engine shut downs when riding in wet conditions.

Some of the “03” bikes came from the factory equipped with hoses attached to the carburetor vents. These hoses were removed in later production and are not on the “04’s”. Some owners have added vent hoses on their own.

We have found that removing the vent hoses and sealing the area where the rear fender attaches to the air box eliminates the problem.

We suggest that you:

1. Remove the vent hoses from your carburetor.
2. Seal the area where the rear fender attaches to the air box. Duct tape or weather stripping can be used to seal this joint.

If you have any questions about this procedure please call Ryan Young Products 1-800-607-8742



These pictures show the fender to air box joint before and after sealing.



➔ This picture shows the fender to air box joint before sealing.



➔ This picture shows the joint sealed with duct tape. Weather stripping can also be used.